
Observation Details

Id: 2
Unit id: 1

Department id: 43

Area id:

Fap area id: 150

User id: 133

Mat code:

Observation condition: 3

Condition type: 6,7,4

Description: Due to rain water

Recomondation: recomondation authority

Action taken:

Photo:



Priority: 2

Observation status: 1

Violation by: 0

Violator name:

Violation reason:

Violation id:

Employee id:

DI:

Fine status: 2

Challan image:

Type: 1

Assign to:

Assign description:

Worker id:

Close photo:

Close description:

Close datetime:

Created at:

Updated at: